Work Order (Bid Form)

| WORK ORDER INFORMATION |
|------------------------|
|------------------------|

| WORK ORL | ER INFO | <u>PRMATION</u> | | |
|-------------|--------------------|---------------------------|---------------------------------------|--|
| Work Or | | Weatherization MADISON | | |
| CLIENT INF | ORMATI | <u>ION</u> | | |
| Client Na | me: | | Address. | the state of the s |
| Client | : ID | week at a sec | | · · · · · · · · · · · · · · · · · · · |
| Alt. Client | t <i>ID:</i> 16016 | 6SW-0626 | | |
| AGENCY IN | IFORMA | <u>TION</u> | | |
| Agency: | SWHRA | | | Agency Phone: (731) 989-5111 |
| Address: | 1574 Whit | te AVE | | Fax: |
| | Hendersor | n, TN | | Email Address: |
| | | | | |
| Company | Name & Li | icense Number: | · · · · · · · · · · · · · · · · · · · | |

COMMENT

Contractor's Signature:

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-424-0276

Client Name: Client ID:

Alt. Client ID: 16016SW-0626

Work Order (Bid Form)

DOE Weatherization Assistant

Work Order Name

Report Run On: 5/21/2010

Version 8.5.0 Page 1 of 6

Measures

| | Measure 1 Seal | Ducts | | | Componen | ts | | I | nspected |
|---|--|---|-------|--------|--------------|-------|--|------------|----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | | 4-4 | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Construction Materials/Hardwar e | Mastic duct boots and check all conections and joints for leaks and repair as needed, Registers had high presure pan readings | Each | 1 | | | Terramental de la constanta de | | |
| 2 | Labor | Labor | Hour | | | | | | |
| (| Other Detail | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| _ | | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |

Report Run On: 5/21/2010

Page 2 of 6

| ı | Measure 2 Gene | eral Air Sealing | | | Component | ts | | ı | nspected |
|---|--|---|-------|--------|--------------|-------|------|--|----------|
| С | omment | | | | Estimated | | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Construction Materials/Hardwar e | Seal crown molding and corners in bedroom 1.Hall bath seal pipes under sink,Kitchen seal pipes under sinkand exhaust fan over stove | Each | 1 | | | | | |
| 2 | Labor | Labor | Hour | | | | | ALIPPINE TO THE PROPERTY OF TH | |
| 3 | Construction Materials/Hardwar e | Seal wall behind washer and dryer, seal pipes behind washer, Seal breaker box, Master bath seal pipes under sink and hole in ceiling. Seal crowm in the den hall and the kitchen | Each | 1 | Transport | | | | |
| 4 | Labor | Labor | Hour | | | | | | |
| _ | Other Detail | | | | | | 71 | | |
| L | | | | | | |] [| | |
| L | | | | | 0.4.7.4.6 | |] [] | Sub Total: | |
| Γ | | | | weasur | e Sub Total: | | | | |
| | Field Notes: | | | | | | | | |

Report Run On: 5/21/2010

Version 8.5.0 Page 3 of 6

| | of Fiberglass Loose | | | Component | ts | | i | Inspected |
|---|--|----------------------|----------|------------------------|-------|-----|------------|-----------------|
| Comment | | | | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | Roof Insulation - Fbergls,Blwn | Bag | 48 | | | | | |
| 2 Labor | Labor | Hour | | | | | American | |
| Other Detail | | | | | | , | | |
| | | | | | | | | |
| | | | | | |] | | |
| | | | Measur | e Sub Total: | | | Sub Total: | |
| Field Notes: | | | | | | | | |
| | /H Pipe Insulation | | | Componen | ts | | | Inspecte |
| Measure 4 DW | /H Pipe Insulation | | | | | | Actual | |
| Measure 4 DW | /H Pipe Insulation Description / Comment | Units | | Componen | | Qty | | Inspected Total |
| Measure 4 DW Comment # Material / Labor | | | | Componen: Estimated | | Qty | Actual | |
| Measure 4 DW Comment # Material / Labor 1 Insulation | Description / Comment | Units | Qty | Componen: Estimated | | Qty | Actual | |
| Measure 4 DW Comment # Material / Labor 1 Insulation | Description / Comment DWH Pipe Insulation | <i>Units</i> Each | Qty 1 | Componen: Estimated | | Qty | Actual | |
| Measure 4 DW Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DWH Pipe Insulation | <i>Units</i> Each | Qty 1 | Componen: Estimated | | Qty | Actual | |
| Measure 4 DW Comment # Material / Labor 1 Insulation 2 Labor | Description / Comment DWH Pipe Insulation | Units Each Each | Qty 1 1 | Componen: Estimated | | | Actual | |

Client Name:

Client ID: Work Order Name:

Alt. Client ID: 16016SW-0626 Report Run On: 5/21/2010

Work Order (Bid Form)

DOE Weatherization Assistant Version 8.5.0

Page 4 of 6

| Measure 5 DW | H Tank Insulation | ę | | Componen | ts | | | Inspected |
|--|--|----------------------|---|---|-------|------|--|-----------|
| Comment | | | | | | | | |
| | | | *** | Estimated | | | Actual | |
| # Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 Insulation | DWH Tank Insulation | Each | 1 | 777777777777777777777777777777777777777 | | | | |
| 2 Labor | Labor | Each | 1 | | | | | |
| Other Detail | ; | | |) [:[- | | 7 | [| |
| | | | | | |] [] | | |
| | | | | | | | | |
| | | | Measur | e Sub Total: | |] ; | Sub Total: | |
| Field Notes: | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Measure 6 CO | Monitor is Needed | | *************************************** | Component | ts | | Acceptance of the second of th | Inspected |
| Measure 6 CO Comment | Monitor is Needed | | ************************************** | Component | ts | | | Inspected |
| | Monitor is Needed | | | Component | | | Actual | Inspected |
| | Monitor is Needed Description / Comment | Units | Qty | • | | Qty | | Inspected |
| Comment | Description / Comment | <i>Units</i> Each | Qty 1 | Estimated | | Qty | Actual | |
| Comment # Material / Labor 1 Health and Safety | Description / Comment | | | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items | Description / Comment CO monitor | Each | 1 | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment CO monitor | Each | 1 | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment CO monitor | Each | 1 | Estimated | | Qty | Actual | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment CO monitor | Each Hour | 1 | Estimated | | | Actual | |
| # Material / Labor 1 Health and Safety Items 2 Labor Other Detail | Description / Comment CO monitor | Each Hour | 1 | Estimated Unit Cost | | | Actual Unit Cost | |
| Comment# Material / Labor1 Health and Safety Items2 Labor | Description / Comment CO monitor | Each Hour | 1 | Estimated Unit Cost | | | Actual Unit Cost | |
| # Material / Labor 1 Health and Safety Items 2 Labor Other Detail | Description / Comment CO monitor | Each Hour | 1 | Estimated Unit Cost | | | Actual Unit Cost | |

Client Name: Client ID: Alt. Client ID: 16016SW-0626

Work Order Name:

Report Run On: 5/21/2010

| | <i>Measure</i> 7 Pres | sureRelief Piping Need | ded | | Componen | ts | | I. | nspected |
|---|-------------------------|------------------------|--------|----------|--------------|----------|------|------------|----------|
| C | omment | | | | | | | | |
| | | | | | Estimated | <u> </u> | | Actual | |
| # | Material / Labor | Description / Comment | Units | Qty | Unit Cost | Total | Qty | Unit Cost | Total |
| 1 | Health and Safety Items | Pressure relief piping | Each | 1 | THEORETE | | | | |
| 2 | Labor | Labor | Hour | 1 | | | | | |
| | Other Detail | | | Measur | e Sub Total: | | | Sub Total: | |
| | Field Notes: | | | | | | | | |
| | | | Work O | rder Gra | nd Total: | | Gran | d Total: | |

Client Name: Client ID: Alt. Client ID: 16016SW-0626 Work Order (Bid Form)

Work Order Name:

Report Run On: 5/21/2010

Page 6 of 6